

LOCATION MAP





Client: Kessinger/Hunter and Company

Camera Make: Kodak

Job Number: 04-4343

Site Address: Vicinity of 18th Street and The Paseo

Site Location: Kansas City, Missouri

Photographer: Date: Direction: Comments: B. Busch Sept. 30, 2004 NW

Employment service center located northwest and

north of subject property



Photographer: Date: Direction: Comments: B. Busch Sept. 30, 2004 NE

Intersection of 18th Street and The Paseo, located north/northeast of subject property



Client: Kessinger/Hunter and Company

Camera Make: Kodak

Vicinity of 18th Street and The Paseo Kansas City, Missouri Site Address:

Site Location:

Photographer: Date: Direction: Comments:

B. Busch Sept. 30, 2004

NE

Office/retail building located northeast of subject property



Job Number: 04-4343

Photographer: Date: Direction:

B. Busch Sept. 30, 2004

Comments: Office/retail building located east of subject property

Job Number: 04-4343

Client: Kessinger/Hunter and Company

Camera Make: Kodak

Site Address:

Vicinity of 18th Street and The Paseo

Kansas City, Missouri Site Location:

Photographer:

Date: Direction: Comments:

B. Busch Sept. 30, 2004 SE

Church located east of subject

property



Photographer: Date: Direction:

B. Busch Sept. 30, 2004

NĖ

Comments: Vacant lot located east and southeast of



Client: Camera Make: Kessinger/Hunter and Company

Kodak

Site Address:

Vicinity of 18th Street and The Paseo

Site Location:

Kansas City, Missouri

Photographer: Date: Direction:

Comments:

B. Busch Sept. 30, 2004 NW

Vacant commercial building located south of subject

property



Photographer: Date: Direction: Comments:

B. Busch Sept. 30, 2004 NW

Metal door manufacturing facility located southwest and west of subject property



Bolo Salars

Job Number: 04-4343

Client: Kessinger/Hunter and Company


Camera Make: Kodak

Site Address: Vicinity of 18th Street and The Paseo

Site Location: Kansas City, Missouri

Photographer: Date: B. Busch Sept. 30, 2004

Direction: Comments: SW Parking lot located west of subject property



Job Number: 04-4343


Photographer: Date:

B. Busch Sept. 30, 2004 SW

Direction: Comments:

Overview of south subject building (vacant

YMCA Building)



Brigas Np

Client: Kessinger/Hunter and Company

Camera Make: Kodak

Vicinity of 18th Street and The Paseo Kansas City, Missouri Site Address:

Site Location:


Photographer:

B. Busch Date: Sept. 30, 2004 Direction: N/A

Comments:

gymnasium, with surrounding overhead track, in west portion of first floor

Interior of



Job Number: 04-4343

Photographer: Date:

B. Busch Sept. 30, 2004 N/A

Direction: Comments:

Additional view of overhead

track



Client: Kessinger/Hunter and Company

Camera Make: Kodak

Site Address: Vicinity of 18th Street and The Paseo

Kansas City, Missouri Site Location:

Photographer: Date: Direction: Comments:

B. Busch Sept. 30, 2004

N/A

Remnants of forced-air furnace

adjacent to gymnasium



Job Number: 04-4343

Photographer: Date:

B. Busch Sept. 30, 2004

Direction: N/A Comments:

Example of skylight; above aforementioned furnace

remnants



Client: Kessinger/Hunter and Company

Camera Make: Kodak

Site Address:

Vicinity of 18th Street and The Paseo

Site Location: Kansas City, Missouri

Photographer: Date: Direction: B. Busch Sept. 30, 2004

Direction: N/A
Comments: Typic

Typical firstfloor room



Job Number: 04-4343

Photographer: Date: Direction: B. Busch Sept. 30, 2004 N/A

Comments: Additional first-

floor room



Client: Kessing
Camera Make: Kodak

Kessinger/Hunter and Company Kodak Job Number: 04-4343

Site Address:

Vicinity of 18th Street and The Paseo


Site Location: Kansas City, Missouri

Photographer: Date: Direction: Comments: B. Busch Sept. 30, 2004 N/A First-floor locker room



Photographer: Date: Direction: Comments: B. Busch Sept. 30, 2004 N/A

First-floor shower room



Client: Kessinger/Hunter and Company

Camera Make: Kodak

Site Address:

Vicinity of 18th Street and The Paseo


Site Location: Kansas City, Missouri

Photographer: Date: Direction: B. Busch Sept. 30, 2004

Direction: N/A
Comments: Swin

Swimming pool

in south portion of building



Job Number: 04-4343

Photographer: Date:

Direction:

B. Busch Sept. 30, 2004 N/A

Comments: Drum and

debris in swimming pool



Client: Kessinger/Hunter and Company

Camera Make: Kodak

Site Address: Vicinity of 18th Street and The Paseo

Site Location: Kansas City, Missouri

Photographer: Date:

B. Busch Sept. 30, 2004

N/A Direction: Comments:

Typical second-

floor room



Job Number: 04-4343

Photographer: Date: Direction: Comments:

B: Busch Sept. 30, 2004 N/A

Second-floor hallway; note paint cans



Kessinger/Hunter and Company Client:

Kodak Camera Make:

Site Address:

Vicinity of 18th Street and The Paseo

Site Location: Kansas City, Missouri

Photographer: Date: Direction: Comments:

B. Busch Sept. 30, 2004

N/A

Typical thirdfloor room



Job Number: 04-4343

Photographer: Date:

B. Busch Sept. 30, 2004

Direction: Comments: N/A Typical fourthfloor room



Client: Kessinger/Hunter and Company

Camera Make: Kodak

Site Address: Vicinity of 18th Street and The Paseo

Site Location: Kansas City, Missouri

Photographer: Date: Direction: B. Busch Sept. 30, 2004 N/A

Comments: Protruding pipe

and capped feature in lower level of east portion of building



Job Number: 04-4343

Photographer: Date: Direction: Comments: B. Busch Sept. 30, 2004 N/A

Area of dark staining near bags of lime and silica in lower-level room



Client: Kessinger/Hunter and Company Job Number: 04-4343
Camera Make: Kodak

Site Address: Vicinity of 18th Street and The Paseo

Site Location: Kansas City, Missouri

Photographer: Date: Direction:

Comments:

B. Busch Sept. 30, 2004 SE

Vegetative overgrowth and limited solid waste located

north of building



Photographer: Date: Direction: Comments: B. Busch Sept. 30, 2004 N/A

Additional area of limited solid waste, adjacent to building



Client: Kessinger/Hunter and Company

Camera Make: Kodak

Site Address: Vicinity of 18th Street and The Paseo

Site Location: Kansas City, Missouri

Photographer: Date: Direction: Comments:

B. Busch Sept. 30, 2004 NW Vacant lot located north of building



Job Number: 04-4343

Photographer: Date: Direction: Comments:

B. Busch Sept. 30, 2004 NW Overview of vacant gas station on north portion of



Client: Kess

Kessinger/Hunter and Company

Camera Make: Kodak

Site Address: Vicinity of 18th Street and The Paseo

Site Location: Kansas City, Missouri

Photographer: Date: B. Busch Sept. 30, 2004

Direction: NW Comments: Clos

Closer view of vacant gas

station building and pump canopy; monitoring well cover visible at

lower center of photo

July gold



Job Number: 04-4343

Photographer: Date:


B. Busch Sept. 30, 2004

Direction: NW

Comments: Former pump

area under canopy; large concrete cut-out is present in this

area



Client: Kessinger/Hunter and Company

Camera Make: Kodak

Site Address:

Vicinity of 18th Street and The Paseo

Site Location: Kansas City, Missouri

Photographer: Date: Direction: B. Busch Sept. 30, 2004 NW

Comments: Additional large

concrete cut-out located west of gas station building; reported former location of USTs



Job Number: 04-4343

Photographer: Date: B. Busch Sept. 30, 2004

Direction: SE Comments: Add

Additional view of the

aforementioned concrete cut-out



Client: Kessinger/Hunter and Company

Camera Make: Kodak

Site Address: Vicinity of 18th Street and The Paseo

Site Location: Kansas City, Missouri

Photographer: Date: Direction: B. Busch Sept. 30, 2004 SW


Comments: Limited solid

waste on southwest portion of gas station parcel



Job Number: 04-4343

Photographer: Date: Direction: Comments: B. Busch Sept. 30, 2004 SE Small storage shed on southwest portion of gas station parcel



Client: Kessinger/Hunter and Company

Camera Make: Kodak

Site Address:


Vicinity of 18th Street and The Paseo

Site Location: Kansas City, Missouri

Photographer: Date: Direction:

Comments:

B. Busch Sept. 30, 2004 N/A Interior of storage shed



Job Number: 04-4343


Photographer: Date: B. Busch Sept. 30, 2004 W


Direction: W
Comments: Example of


covered monitoring well on gas station parcel




USGS TOPOGRAPHIC MAP














































The Sanborn Library, LLC

Copyright 1931 The Sanborn Library, LLC RAS


EDIT Reason Associate


Reproductive in by the system of the specific control of the system of the s







Adjoining Map









Copyright 1953 The Sanborn Library, LLC RAS

COR Research Associate

Confidence in visiting to part of any year of 17th Earthurn Library, LLC may be perfetted without prior written

Adjoining Map